




Historic, archived document

**Do not assume content reflects current
scientific knowledge, policies, or practices**

1.8
X-75

Light and Ventilation



Good light and a cross draft require a glass door or windows on at least two sides of the kitchen.

Place artificial lights where they will illuminate work centers.

Bureau of Home Economics, United States Department of Agriculture